



Used Ford E-450

VIN # IFDWE45FF22H49829

Color : White

Condition: Not in Running

Exterior faded paint, worn out interior,
without key



Used Mitsubishi Montero V6XLS

VIN# JAAMW31R41J012057

Color : Dark Green

Condition: Not in Running

Slightly Exterior faded paint, worn out interior

Without key



Ford Excursion Bullet Proof

VIN# IFMSU41P64ED60345

Color : White

Condition : slightly exterior faded paint

Interior shield with plastic, Without key



Used Ssang Yong Korando TX5

VIN # KPALA4AD15P43949

Color : White

Condition: Not in Running

Slightly Exterior faded paint, worn out interior

Without key



Used Volvo Vintage Car

VIN #130254

Color : Gray

Condition: exterior faded paint, rusty

Interior faded paint & rusty , without key



Kia Bongo Ambulance

VIN#KRFEABD327B031179

Condition: Exterior faded paint

Junk inside, Not running , without key



Toyota (Unknown Model)

Knockdown – Body Only

Frame No. HDJ81-041479



Used Cadillac Gines

VIN# LG6DW52D1SR702563

Color : Midnight Blue

Condition: Not running

Exterior faded paint, dented body, worn out interior, flat tires & without key



Used Dodge Caravan SE Chrysler Wagon

VIN # DGBC284GH4538SR223937

Color : Maroon

Condition : not in running

Exterior faded paint, worn out interior, without key



Used Mercedes Benz S500

VIN # WDBNG75J3AA387704

Color : Midnight Blue

Condition: Not in Running, Flat Tire, without key

Exterior faded paint, worn out interior



Used Mercedes Benz Sedan

VIN # Unknown

Color : Black

Condition: Not in Running, Flat Tire, without key



Used Mercedes Benz C-230

VIN#WDB6024111D288445

Color : Black

Condition: Not in Running, without key

Exterior faded paint, worn out interior



Used Mercedes Benz 310D

VIN # WDB6024111D288445

Color : Beige

Condition: Not in Running, Flat Tire, without key

Exterior faded paint, worn out interior



Used Ford Triton VIO

VIN # IFDXE4059WHA32153

Color : White

Condition: Not in Running, without key

Exterior faded paint, worn out interior



Mercedes Benz Daimler Chrysler Diesel
VIN# WDB210061A006711
Color : Black
Condition: Not Running



Lexus RX 300 (Automatic)
VIN # JTGHE10U5Y0096043
Color : White
Condition : Not Running



Daihatsu Move (RHD) VIN# Unknown
Color : Black
Condition: Not Running, dilapidated interior,
Exterior faded paint.




Mazda 5
VIN # JM1CR2W35AO383905
Color : Blue
Condition: Not Running, exterior faded
paint and interior



Toyota Camry LE
VIN# JT2SK12E9R0208451
Color : Black
Condition: Not Running,
faded paint and interior



Asia Motors Medical Bus
Color : Blue
Condition: Not Running, faded paint
interior



Lexus ES300
VIN# JTHBF30G325034850
Color : White
Condition: Not Running
faded paint



Hyundai Sonata LPG
VIN # HKMHEU41MDGA165505
Color : Beige
Condition : Not Running, broken doors, faded
paint



Mercedes Benz S 500
VIN# WDB2201751A021444
Color : White
Condition: Not Running , faded paint, flat tire



BMW
VIN # WBAFJ910108482860
Color : Light Brown
Condition : Not Running, faded paint



Mercedes Benz 200TD
VIN# WDB1241801F081687
Color : White
Condition: Not Running , faded paint



Toyota V8 SR Sequoia
VIN # 5TDZT34A63S13936
Color : Red
Condition : Not Running, faded pain



Unknown Car Knockdown

Mercedes Benz C320
VIN# WDBHA23EXVF582128
Color : White
Condition : Not Running, faded paint



Ford Mustang Scrap



BMW Front Cut with Engine



Cabin Trailer SOLIFER